

DATE March 10, 2026
REFERENCE Software Update
PRODUCT RDP-01T

A design improvement has been implemented on the Westermeyer Industries' model RDP-01T differential pressure monitor.

A software update has been implemented on devices shipped after 3/3/2026. This software update assists in stabilizing the output voltage from the device by softening the refresh rate and removing frequent pressure spike readings caused by compressor cycling.

At this time, the software update cannot be flashed in the field, so a new device – including pressure transducers, must be purchased to receive this new feature.

If there are any questions about this change, please contact your Westermeyer sales representative for more details.

